



Here when it hit the blade holders. You are seeing the blade holders have been ground one side. This is because I thought by doing this way would resolve the problem. But it does not.

